

## Configure Input Parameters

Number of sensors

2

## Sensor Configuration

	Sensor 1	Sensor 2
Sensor Name	Temperature (°C)	Air pressure (mbar)
Sensor Conversion	$-66.875+43.75*V$	$625*(0.2V-0.1)+700$
Sensor Gain	1.11	1.11
Min. Output	0.5	4.5
Max. Output	0.5	4.5

## Enter Channel details

Number of Channels

1

Channel	First sensor	Second Sensor	Device Number	Min. Input	Max. Input	COR-Relation Routine
Channel 1	1	2	From list of devices	0	5	1